

# Public Meeting on Straight Creek Tributaries in Lee County

October 21, 2008





### Why Are We Here?

- Learn about water quality in six Straight Creek tributaries
- Explain efforts that the State is undertaking to improve and protect water quality
- Learn what you can do to help








#### What's the Status of these Tributaries?

- DEQ routinely monitors the quality of waters across the state and reports those results every 2 years
- In every report since (1996), all six Straight Creek tributaries were listed as "impaired" because of low biological monitoring scores.





# Biologically Impaired Tributaries in the Straight Creek Watershed



#### **Biological Impairment**


#### What does impaired mean?

• The biological monitoring score was below the impairment threshold of 60.


#### What is the standard?

• DEQ uses the general standard which states "All state waters, including wetlands, shall be free from substances attributable to sewage, industrial waste, or other waste in concentrations, amounts, or combinations which contravene established standards or interfere directly or indirectly with designated uses of such water or which are inimical or harmful to human, animal, plant, or aquatic life. "


# What Are Biological Monitoring Scores in Ely Creek & Tributaries?




### What Are Biological Monitoring Scores in Stone Creek?




### What Are Biological Monitoring Scores in Puckett Creek and Lick Branch?




# What Are Biological Monitoring Scores in Bailey's Creek?



## What Are Biological Monitoring Scores in Gin Creek?



# Impaired Tributaries: What is harming the Aquatic Life?



### Straight Creek Tributaries Probable Stressors

Stream Stressor(s)

Ely Creek Total Dissolved Solids (TDS)

Stone Creek Total Dissolved Solids (TDS)

Puckett Creek Total Dissolved Solids (TDS)

Lick Branch Sediment, TDS & pH

Bailey's Trace Sediment & TDS

Gin Creek Sediment & TDS





#### What Happens When a Stream is Impaired?

• The State begins a formal process to clean up that water body (a TMDL)

> **Implementation** Plan

We are here

Study





• Identifies permit controls or best management practices needed to make necessary pollutant reductions





Maximum

Daily

Load

Clean

**Monitoring** 

Water quality standards met






• Estimates necessary pollutant reductions

• Calculates amounts from each source

• Identifies sources of pollution



The Process

#### What are the Study Goals?

- Identify causes of the biological impairments (stressors)
- Quantify amounts of each stressor
- Determine an appropriate endpoint for each stressor
- Estimate reductions necessary to meet the water quality standard





#### What Can You Do to Help?

- Participate on the Technical Advisory Committee
  - Group of local citizens, landowners, organizations, and government entities that will provide input, review and assistance to DEQ during the study
  - Goal make sure technical aspects of the study are accurate as well as acceptable to the community





### Recap

- Biological impairments in six Straight Creek tributaries including:
  - Ely Creek, Stone Creek, Puckett Creek, Lick Branch, Bailey's Trace and Gin Creek.
- DEQ is beginning a Water Quality Study to investigate these impairments
- Study will be followed up by developing an implementation plan to reduce the pollutant levels found to be causing the problems.



### **Questions?**

#### **Shelley Williams**

Department of Environmental Quality
Regional TMDL Coordinator
355 Deadmore Street
P.O. Box 1688
Abingdon, VA 24212
(276) 676-4845
sdwilliams@deq.virginia.gov

#### **Rod Bodkin**

MapTech, Inc.
3154 State Street
Blacksburg, VA 24060
(540) 879-9294
rbodkin@maptech-inc.com

• Comment period for this public meeting ends Dec. XX, 2008



